



**UL International, L.L.C.
Taiwan Branch**

美商優力安全認證有限公司台灣分公司

UL International, L.L.C., Taiwan Branch

台北市 112 北投區大業路 260 號 1 樓

1st Fl 260 Da-Yeh Road Peitou Taipei City Taiwan 112

電話: 886-2-2896-7790

傳真: 886-2-2891-7644

<http://www.ul.com.tw>

NOTICE OF AUTHORIZATION TO APPLY THE UL MARK

January 5, 2006

Yungtech Electronics Corp.

4th Fl-1 87 Chung Yang Rd Sec 3 Tu-Cheng

Taipei Hsien Taiwan 236

Fax number: (02)2267-1058

Reference: File E249346

Project 05CA56282

Report Reference Number: E249346-A4-UL-1.

Amendment 1.

Product(s): UL/C-UL Investigation for Sound Bar, Models L004JH, L005J8.

Dear Ms. Ann Tseng,

Any information and documentation provided to you involving UL Mark services are provided on behalf of Underwriters Laboratories Inc.

UL's investigation of your product has been completed under the above project number and the subject product was determined to comply with the applicable requirements.

This letter temporarily supplements the UL Follow-Up Services Procedure and serves as authorization to apply the UL Listing Mark only at the factory under UL's Follow-Up Services Program to the subject product which is constructed as described below:

Similar to original product covered in the UL Follow-Up Services Procedure, File E249346, Volume X1, except for employing the alternate shape, circuit and adding the model name of L005J8.

To provide the manufacturer with the intended authorization to use the UL Mark, the addressee must send a copy of this Notice and all attached material to each manufacturing location as currently authorized in File E249346, Volume X1.

This authorization is effective from the date of this Notice and only for products at the indicated manufacturing locations. Records in the Follow-Up Services Procedure covering the product are now being prepared and will be sent to the indicated manufacturing locations in the near future. Please note that Follow-Up Services Procedures are sent to the manufacturers only unless the Applicant specifically requests this document.

Products that bear the UL Mark shall be identical to those that were evaluated by UL and found to comply with UL's requirements. If changes in construction are discovered, appropriate action will be taken for products not in conformance with UL's requirements and continued use of the UL Mark may be withdrawn.

Sincerely,

Answer Sung

Reviewed by:

Patrick Tsai

Answer Sung

Engineer

UL International, L.L.C., Taiwan Branch

Tel: 886-2-28907467

Fax: 886-2-28907443

E-mail: Answer.Sung@tw.ul.com

Patrick Tsai

Associate Project Engineer

UL International, L.L.C., Taiwan Branch

E-mail: Alex.Huang@tw.ul.com

CC: Universal Standard Service Inc.

Fax: (02)2608-1259

Attn: Ms. Emily Kao

An independent organization working for a safer world with integrity, precision and knowledge.

